




Terrasoft®

Cable crossing



The temporary or permanent covering of hoses or cables is often a challenge in traffic. The cable bridges must be able to be driven over by all vehicles (including trucks), calm the traffic and protect the underlying cables.


The Terrasoft cable crossing made of pure rubber granulate meets all the requirements for cable bridges. The material is dimensionally stable and yet soft, so that no damage to transiting vehicles arises because the ramps are almost at ground level. Moreover, the individual elements each weighing 18 kg are quite light, so they can be installed and removed quickly. To further increase traffic safety, the Terrasoft cable crossing is equipped with triangular reflectors that are visible from afar.

ADVANTAGES

- frost proof
- quick and easy installation
- temporary cover of cables or hoses on roadways
- high visibility through reflectors

APPLICATION

The Terrasoft cable crossing is used on roads and paths and covers cables or supply lines, for example, at festivals and public events. Even with push-chairs, rollators or wheelchairs it is easy to drive over.



Gluing the Terrasoft cable crossing on firm substrate and at the front sides – for permanent use!

INSTALLATION INSTRUCTIONS

It is recommended to apply a spot adhesive with the cartridge adhesive (P / N 452500131). Here, the cable crossings are glued together on the front sides.

On private properties, the Terrasoft cable crossing can also be glued to the substrate. A temporary removal is then no longer possible.

Notes to selective gluing:

Pierce the membrane in the threaded part of the adhesive cartridge and screw on the cut plastic nozzle. Using a screwdriver, remove the bottom plate of the cartridge and insert it into the manual or pneumatic gun.

The bonding takes place on the completely cleaned underground by means of adhesive dots on the back side of the two beiden Kerbstone ramps. According to local belongings

(e.g. snow-clearer, mechanical road cleaning etc.) the cable crossing must be temporarily removed. So just glue the cable crossings together at the herms, Do NOT glue them with the ground.

The surface and ambient temperature must be at least 5 ° C. The Elements should only be glued in dry weather. Adhesive cartridges must not be stored below 10 ° C.



Terrasoft Cable crossing
black

Colours



-13x
black

Specifications



Spare parts



4525001x1
Gluing